



CURVE SHOWN AT CONDITION NO. 2  
ASSUMED WORST CONDITION

INTACT STABILITY CURVE

POINTS OF IMMERSION					
NO.	DESCRIPTION	X AFT ST. 0	Y OFF C	Z ABOVE DLWL	REMARKS
1	COMPANION WAY SILL	26.75'	0.75'	3.50'	
2	L.P.G. LVR. @ 'T'	31.66'	2.16'	3.00'	
3	SHEER @ X	16.10	6.00'	4.70'	
4	TRANSOM CORNER @ KNUCK	34.9'	3.33'	4.29'	
5	STGM AT KNUCKLE	-4.33'	0	5.04	
6	DECKHOUSE @ DECK	20.0'	4.0'	4.93	



J. Simpson Ltd.  
Marine Designers & Constructors  
4876 59th Street  
Delta, B.C.  
Canada V4K 4L7

"FELICITY"  
40' FLUSH DECK CUT  
# 86-390